



The TAWERS-WG4 Arc Welding System is suitable for CO₂, MAG, MIG and Stainless Steel welding applications.

TAWERS WG4 Arc welding system

Key Features

Highly accurate and efficient welding experience

Easier to use with touch panel and 3D display

For manufacturing where everything is connected

Cables arranged on the back to save space

TAWERS WG4 Arc welding system

<https://ap.connect.panasonic.com/sg/en/products/robots-welding/tawers-wg4-arc-welding-system>

Other Input/Output Signal	Dedicated Signal: Input 6 points, Output 8 points
	General purpose signal: Input 40 points, Output 40 points
	Safety Input/Output: Input 8 points, Output 8 points
Input Power Supply	3-phase, AC200 V (+-10%), 50 Hz/60 Hz (+-2%)
	40,000 points
	Software Servo System
	TP: SD memory card slot x 1
	USB2.0 (Hi-speed supported) x2
	Simultaneous 6 axes (max. 27 axes)
	14 mm ² (AWG6) or more
	14 mm ² (AWG6) or more
	CO ₂ /MAG/Stainless Steel MIG
	Pulse MAG/Stainless Steel pulse MIG
	30 A-350 A DC
	12 V-36 V DC
	10 Minute Cycle
	CO ₂ /MAG/Stainless Steel MIG: 80%
Pulse MAG/Stainless Steel pulse MIG: 60 %	